

DOORWAY AT ROOM 8114, LARGE GAP AT BOTTOM OF HOLLOW
METAL DOOR FRAME

PHOTO # 1



LEKTREIVER HIGH DENSITY FILING SYSTEM
INSIDE ROOM 8114

PHOTO # 2



ROOM 8403, MAP FILE IN THE COE
CONSTRUCTION OPERATIONS

PHOTO # 3



ROOM 8006, SMALL SAFE IN ACCOUNTING
AND FINANCE OFFICE

PHOTO # 4




ROOM 8433A, FIVE (5) DRAWER SAFE

PHOTO # 5



ROOM 8437, LARGE RADIO

PHOTO # 6



ROOM 8313, LARGE DEFLECTION AT DOORWAY FROM CORRIDOR
INTO CONFERENCE ROOM

PHOTO # 7



ROOM 7021, LEKTRIEVER INSIDE COE SPACE

PHOTO # 8